"BROWN SOUND"
Amp Slaving

AMP 1

AMP 2

LOAD

STL-1

LEVEL

INPUT   THRU

OUTPUT

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

"BROWN SOUND"
Amp Slaving

AMP 1

AMP 2

LOAD

INPUT   THRU

OUTPUT

STL-1

LEVEL

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

"BROWN SOUND"
Amp Slaving

AMP 1

AMP 2

LOAD

STL-1

LEVEL

(FX UNIT)

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

"BROWN SOUND"
Amp Slaving

AMP 1

AMP 2

LOAD

EFFECTS

STL-1
LEVEL

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

AMP 1

POWER AMP

LOAD

EFFECTS

STL-1

LEVEL

INPUT   THRU   OUTPUT

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

"WET / DRY / WET"

AMP 1

POWER AMP

LOAD
(DRY CAB)

EFFECTS

(FX - LEFT)

(FX - RIGHT)

STL-1

LEVEL

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com

DIRECT RECORDING
31 Band EQ recommended

AMP 1

LOAD

EQ or EFFECTS

PRO TOOLS COMPAQ

STL-1
LEVEL

INPUT THRU OUTPUT

LOAD = Speaker (reactive) or Resistor (resistive)

www.voodooamps.com